MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hookins University Baltimore, Maryland 21218 (301) 235-0771

COUNTIES (MD/PA)	WASHINGTON/FRANKLIN
M&D milestone no	102 (105)
MHT-HSI no.	WA-I-487
PROTECTION ENDANGERED MASSING	

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5'quadrangle Hagerstown 1953, original site/MXXXX/date 1767, redetermined 1902 UTM 18.26766.440009 bench mark/datenone observed Off S/S Oaks Road, State Line, PA-MD. About 3/4 mile ESE of center of village of State Line; at point 0.7 mile E of US 11 at the Line & 0.25 mile SE of Oaks Rd; unmarked, in the middle of a level, unfenced cornfield; about 1200' due W of the James R. Petre farmhouse. Cannot be seen from any rd any season. DIRECTIONS TO SITE:

From M&D 101 (104): continue W on Reid Rd about 1.35 miles to its junction with Oaks Rd; turn right & follow a short distance (about O.1 mile), then bear left (still on Reid Rd) about 0.15 mile to Middle Woodland Parkway; turn right (NE) (over) DESCRIPTION/MEASUREMENTS: original/xxplxxxx/xxplxxxx/date 1767; repaired & reset DESCRIPTION/MEASUREMENTS: original/replikes/replacements/date 1767; repaired & reset 1902; squared oolitic limestone post; standing about 1' above ground

N face (PA): 104" wide x 11½" high; P clear, circle panel visible; no fluting or margins remain; surface badly scarred; big chip top NE corner

E face: 11" wide x 12" high; fluting but no margins remain; scarred; big chip top NE corner; chips alledges

S face (MD): 10½" wide x 10½" high; M clear; no circle panel, fluting or margins remain; big chips all edges & corners; scarred surface

11" wide x 9½" high; some fluting discernible, no margins; big chips all edges & corners

no planes or fluting remain; big chips all corners & edges;

weatherworn

none indicated on maps; none observed bench mark:

1900-03 Resurvey notes (order no. 109, as in MGS Vol. 7, 1908, p. 90

105. Milestone No. 102, M. & D., 1767. In an open field southeast of a piece of woods. About three quarters of a mile east of the village of Middleburg. The old monument had been broken off below the surface of the ground (over)

1950 Inspection notes (present order no. 103, photo no. 102) as in Bayliff, 1959, Appendix C, p. 90

105. Original monument slightly chipped on all sides, badly on northeast corner. Foundation solid; lettering clear. Exposed to farm machinery.

1979-81 Inspection notes: order no. 102 (105); photos/negatives/slides no.102(105) 102 (105). Original M&D milestone of 1767, repaired with iron clamps and bands and reset 1902 in redetermined site; in place, in fair condition, firmly set. Letters clear, but all surfaces weatherworn, scarred and chipped. Endangered by farm machinery. SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones

, P. 32 , deed 658 / 122 , acres 50.67 tax map 10, block Leroy L. Martin

301/739-3915 Phone: , deed , acres , block , P. PA: tax map

RECORDED BY: names, addresses, phones, dates Alice Martin 10/13/80 Phone: 301/472-2128 14308 Mount Ave., Phoenix, MD 21131 Assisted by Clyde E. Martin; pointed in right direction by James Petre!

Also see: reverse side X , B&W photos X , negatives X , color slides X , maps XMHT-HSI form , other

DIRECTIONS TO SITE, continued

& follow to its end at another leg of Oaks Rd (about 0.4 mile); cross rd & pick up gravel lane leading (about 0.3 mile) to the Leroy Martin farm, run by his son-in-law, James Petre. Park here & ask for permission to record milestone. Unless inspected after crop is harvested, it will be almost impossible to find. But the Petres know where it is & are helpful. Walk about 1000' back along the farm entrance lane (100' short of the white board gate to fenced field on E/S), then head SW (perpendicular to lane) to a point about equidistant from lane & telephone line, & stone site.

CONDITION OF MARKER/FOUNDATION, continued

1900-03 Resurvey notes:

and its position was lost. The proper place was redetermined by the survey and the base of the stone was found by digging. After being repaired with iron clamps and bands the monument was reset.

NOTES

Mr. & Mrs. James R. Petre, 1252 Woodland Parkway, Waynesboro, PA 17268

MGS will want to contact the Petres and make arrangements to mark this stone, for it is obviously damaged by farm machinery (past and present). They are a young, hardworking, cooperative family, and I'm sure they would be glad to help protect the stone, especially if given some more information and encouragement.

B&W PHOTOS/NEGATIVES

5x7 NE corner (1980.24.15), Alice Martin 10/13/80

5x7 SW corner (1980.24.10), "

3½x5 Closeup of top & S/S (1980.24.18), " "

3½x5 View SE: toward Clyde standing on stone & farm buildings (1980.24.9),
Alice Martin 10/13/80

COLOR SLIDES

2x2 NE corner (1980.25.10), Alice Martin 10/13/80

2x2 S/S & top (1980.25.9), "


2x2 View SE: toward Clyde on stone & farm buildings (1980.25.8), Alice Martin 10/13/80

2x2 View due E: toward stone & farm (southerly) barn (1980.25.12), Alice Martin 10/13/80

MAPS

USGS 7½ topographic quadrangle section 1900-03 Resurvey engineer's map (Plates XXXVIII & XXXIX), updated MD tax map section

OTHER





MA-I-487

MA-I-487

MA-I-487

SALERNELL (-/M

PHOTO: ALICE MARTIN 15 13 184 (1975-20)



MASON & DIXEN WEST LINE: MILESTONE 102 (105)

CLINE MARTIN STANDING ON STONE

DIEW LOCKING— SE TOWARD JAMES PETRE

MARM

PHOTO: ALKE MARTIN 10/13/80 (1980.24.9)



WA-1-487 MASSING INNOVALLATIONE MICESTERE 122 12 OFF SEKS CARS EL, STATE LAUX, TX JAMES PETER CARRENT SR TRUSKED PARTE - ALVERT 121 - 180 181 - 20 - 18)



"1168 WA-I-487

MASON & DIXON WEST LINE!
MILESTONE 102 (105)
3/5 & TOP

1/2 2765

PHOTO: ALICE HARTIN 10/13/80 (1980. 24.18)